

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

VIN:	W1N167117XXXXXXX		
Mileage:	89,253 km		
Date:	7/15/2026, 11:39		
Car brand:	Mercedes		
Car series:	GLE	65	8 (12%)
Car model:	GLE C167	Checked Systems	Systems with issues
Build year:	2023		
Fuel type:	Hybrid		
Report ID:	6a57553b88bd0c6979c6a3e3		
Adapter ID:	CST63FFFFFF		

The retrieved FIN matches the FIN stored in the report

Digital



The OBD diagnosis enables the reading of error codes and operational data from the vehicle's control units. This technology supports the identification of potential issues and irregularities. However, it should be noted that not all errors or issues in all control units can be fully detected through OBD diagnostics. Carly Solutions GmbH & Co. KG assumes no liability for undetected errors that are beyond the scope of this diagnostic technology.

Systems with issues

Total: 8

ESP control unit

Fault Code	Status*	Mileage*	Fault Text
U0427	Active	88,960 km	POWER_MODE_BACKUP_FAILURE

IC Instrument cluster

Fault Code	Status*	Mileage*	Fault Text
P1C5C	Active	-	The battery discharge protection is activated.

The information marked with (*) is optional and not available for every fault code. Some technical terms are shown in English because they come directly from the vehicle or manufacturer systems.

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

Systems with issues (continued)

Total: 8

N68 - Electrical power steering (ES)

Fault Code	Status*	Mileage*	Fault Text
B210F	Active	81,616 km	Input "Circuit 30" has a malfunction.
U0427	Active	88,960 km	Implausible data were received from the electronic ignition lock.

N162 - Ambiance light (AML)

Fault Code	Status*	Mileage*	Fault Text
U1127	Active	89,248 km	Communication with one or more color unit and coupling modules on LIN bus 6 has malfunctioned. The message is missing.
U1126	Active	89,072 km	Communication with one or more color unit and coupling modules on LIN bus 5 has malfunctioned. The message is missing.
U1125	Active	89,072 km	Communication with one or more color unit and coupling modules on LIN bus 4 has malfunctioned. The message is missing.
U1124	Active	89,072 km	Communication with one or more color unit and coupling modules on LIN bus 3 has malfunctioned. The message is missing.
U1123	Active	89,072 km	Communication with one or more color unit and coupling modules on LIN bus 2 has malfunctioned. The message is missing.
U1122	Active	89,072 km	Communication with one or more color unit and coupling modules on LIN bus 1 has malfunctioned. The message is missing.

Front SAM Module

Fault Code	Status*	Mileage*	Fault Text
U0168	Active	88,960 km	Communication with the electronic ignition lock has malfunctioned. There is an implausible signal.

The information marked with (*) is optional and not available for every fault code. Some technical terms are shown in English because they come directly from the vehicle or manufacturer systems.

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

Systems with issues (continued)

Total: 8

Front SAM Module

Fault Code	Status*	Mileage*	Fault Text
B22A3	Active	-	The "roof operating unit" control unit is malfunctioning. The voltage value is outside the permissible range.

N2/10 - Supplemental restraint system (SRS)

Fault Code	Status*	Mileage*	Fault Text
C42782	Active	89,248 km	Generic Fault 0100

N10/8 - Rear signal acquisition and actuation module (Rear SAM)

Fault Code	Status*	Mileage*	Fault Text
B22D7	Active	88,640 km	The seat ventilation of the "front left seat" has malfunctioned. The current has fallen below the limit value.
B164B	Active	80,912 km	The rear right blinker light has malfunctioned. There is an internal electrical fault.

N62 - Parking system (PARK)

Fault Code	Status*	Mileage*	Fault Text
A23209	Active	86,976 km	Generic Fault 0100

The information marked with (*) is optional and not available for every fault code. Some technical terms are shown in English because they come directly from the vehicle or manufacturer systems.

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

Systems without issues

Total: 57

N73 - Electronic ignition lock (EZS)	N69/4 - Right rear door (DCU-RR)
N73 - Electronic ignition lock (EZS)	Door module FL
Electronic ignition lock	Active suspension
Battery management system (BMS)	Sound generator for exhaust system
EZS Gateway	E1n9 - Left headlamp (SG-SW-L)
Central Gateway Control Unit	E2n9 - Right headlamp (SG-SW-R)
Control unit 'Powertrain' (PTCU) AMG	N22/1 - Air conditioning (AAC)
48-V on-board electrical system battery	Power electronics (SG-EM)
48-V on-board electrical system battery	N69/5 - KEYLESS GO (KG)
48-V on-board electrical system battery	Distronic
Engine controller	N118 - Fuel pump control unit (FSCU08)
Stationary heater	A40/12 - Head-up display (HUD)
DRVU3	N112/9 - Control unit for telematics services (HERMES)
B84/14 - Augmented reality camera (KAR)	N22/1 - Air conditioning (AAC)
Crash sensor, high-voltage battery	Audio/COMAND operating unit
N26/10 - Car sharing	Shift module
All Wheel drive	A40/11 - Multifunction camera (mono) (MFK)
A40/8 - Head unit display (ZAN)	Backup camera
N69/1 - Left front door (DCU-LF)	N40/3 - Sound system (SOUND)
N69/2 - Right front door (DCU-RF)	Multifunction control unit
N69/3 - Left rear door (DCU-LR)	MTAS Mobile phone cradle (N123/8)
TV Tuner	SG-LML-VL LED matrix of left front lamp unit (E1n11)
Door module FR	Sound generator (SOG)
N69/4 - Right rear door (DCU-RR)	SG-LML-VR LED matrix of right front lamp unit (E2n11)
N69/3 - Left rear door (DCU-LR)	N88 - Tire pressure monitor (TPM)

The information marked with (*) is optional and not available for every fault code. Some technical terms are shown in English because they come directly from the vehicle or manufacturer systems.

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

Systems without issues

Total: 57

Driver seat

Passenger seat

ABA Active Brake Assist (A108)

N121/1 - Tailgate control (HKS)

Active engine mount

AP Airmatic Plus


CSHV Crash Sensor high-voltage battery

Attached is the vehicle inspection report for the VIN
W1N167117XXXXXXX, created on 7/15/2026, 11:39, requested by:
Robert Placen (Vehicle Appraiser)

This account is part of the following organisation:
Placen & Partner Vehicle Appraisers

Car photos

Total: 1



The information marked with (*) is optional and not available for every fault code. Some technical terms are shown in English because they come directly from the vehicle or manufacturer systems.